March 7, 2006





Figure 18. EDS spectra from the region denoted by the red box in Figure 17.

March 7, 2006



Optical photomicrograph showing a cross-section through the inner surface of Joint Section 2. Figure 19.






Figure 20. Backscattered SEM image showing the cross-section of the brass fitting from Joint Section 2. The red numbered arrows indicate areas where EDS spectra were acquired. These spectra are shown in Figure 21, Figure 22, and Figure 23.

March 7, 2006



EDS spectra of the area denoted by arrow #1 in Figure 20. Figure 21.



EDS spectra of the area denoted by arrow #2 in Figure 20. Figure 22.




Figure 23. EDS spectra of the area denoted by arrow #3 in Figure 20.